


ENGINE	112.960 in MODEL 170.466
ENGINE	112.961 in MODEL 203.065 /265
ENGINE	113.992 in MODEL 230.474
ENGINE	113.990 in MODEL 211.076 /276
ENGINE	113.991 in MODEL 215.374, 220.074 /174
ENGINE	113.995 in MODEL 230.472



P09.41-2285-09

Shown on engine 113.990

- | | | | | | |
|---|----------------------------|---|--------------|-------|----------------------------|
| 1 | Air cleaner housing | 4 | Intake lines | 110/6 | Top charge air distributor |
| 2 | Crankcase ventilation hose | 5 | Catches | 110/7 | Gasket |
| 3 | Fitting | 6 | Hose clamps | 110/8 | Bolt |

[illegible]

 Charge air pipe/charge air cooling

Number	Designation		Engine 112.960/ 961 AMG	Engine 113.992/ 993/995	Engine 113.990/ 991
BA09.41-P-1001-01C	Bolt, upper part of charge air distributor to bottom part of charge air distributor	Nm	10	10	9

Repair materials

Number	Designation	Order number
BR00.45-Z-1002-06A	Lubricating paste, rubber parts 2.5 kg, DB supply specification 6867.00	A 000 989 01 60